


# SPARE PARTS LIST

1/2" Reversible Air Drill (Heavy Duty) (Model: AT-4042)



Part No.	Description	Qty.
01	Main housing	1
02	Bolt	1
03	Exhaust deflector	1
04	Cushion	1
05	Air inlet nipple	1
06	O-ring	2
07	O-ring	1
08	Bolt	1
09	O-ring	1
10	Screw	1
11	Lever	1
12	Cover	1
13	Spring	1
14	Screw	1
15	Trigger	1
16	Gasket	1
17	Bearing	2
18	Rear plate	1
19	Rotor	1
20	Rotor blade	5
21	Cylinder	1
22	Bolt	1

Part No.	Description	Qty.
23	Front plate	1
24	Bushing	1
25	Major gear	1
26	Minor gear	6
27	Bolt	6
28	Gear base	1
29	Gear	1
30	Work spindle	1
31	Ring gear	1
32	Bearing	2
33	Fix ring	1
34	Cushion	1
35	Chuck	1
36	Screw	1
37	Chuck key	1
38	Brass ring	1
39	Handle	1
40	Handle grip	1
41	Pin	2
42	Spring	1
43	Front grip	1
44	Rear grip	1